

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	
	:	Examiner: Lamson D. Nguyen
TETSUHIRO MAEDA ET AL.	)	
	:	Art Unit: 2861
Appln. No.: 09/629,093	)	
	:	Conf. No.: 4401
Filed: July 31, 2000	)	
	:	
For: INK JET PRINTING APPARATUS	)	
AND INK JET PRINTING METHOD	:	
FOR FORMING AN IMAGE ON A	)	
PRINT MEDIUM	:	
	)	
U.S. Patent No.: 6,874,864 B1	)	
	:	
Issued: April 5, 2005	)	November 8, 2007

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form is attached..

The amount of \$100.00 to cover the statutory fee for such Certificate of Correction is being paid concurrently; please charge any deficiency in this fee, and credit any overpayment, to Deposit Account 50-3939.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Elizabeth F. Holowacz/  
Elizabeth F. Holowacz  
Attorney for Patentees  
Registration No. 42,667

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
Facsimile: (212) 218-2200  
1716566v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,874,864 B1

DATED : April 5, 2005

INVENTOR(S) : TETSUHIRO MAEDA ET AL.

Page 1 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

“7052465” should read --7-052465--; and

“8025693” should read --8-025693--.

SHEET 18

FIG. 16, “RANDOM” (all occurrences) should read --RANDOM--.

COLUMN 2

Line 10, “36A,” should read --36B,--; and

Line 51, “FIG. 38C to” should read --FIG. 37C to--.

COLUMN 8

Line 42, “such,” should read --such--; and

Line 52, “comprises” should read --comprises--.

COLUMN 9

Line 22, “end” should read --and--;

Line 27, “A1100,” should read --H1100,--; and

Line 41, “51301” should read --H1301--.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO. US 6,874,864 B1**

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

**PATENT NO.** : 6,874,864 B1

**DATED** : April 5, 2005

**INVENTOR(S)** : TETSUHIRO MAEDA ET AL.

Page 2 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 10**

Line 13, "PPC" should read --FPC--;  
Line 18, "contract" should read --contact--;  
Line 43, "outface" should read --surface--; and  
Line 64, "PCS" should read --PCB--.

**COLUMN 11**

Line 7, "(MCB)" should read --(CRPCB)--;  
Line 15, "an the" should read --as the--;  
Line 21, "PCS" should read --PCB--; and  
Line 53, "signal." should read --signal--.

**COLUMN 12**

Line 10, "E1014" should read --E1010--;  
Line 17, "E2006." should read --E1006.--;  
Line 18, "serial." should read --serial--;  
Line 34, "sands" should read --sends--;  
Line 44, "addition" should read --addition,--;  
Line 45, "(PBS)" should read --(PES)--;  
Line 46, "ASP" should read --ASF--; and "(ASPS) should read --(ASFS)--.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO.** US 6,874,864 B1

No. of add'l. copies  
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,874,864 B1

DATED : April 5, 2005

INVENTOR(S) : TETSUHIRO MAEDA ET AL.

Page 3 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 29, "made," should read --mode--;  
Line 41, "control," should read --control--;  
Line 46, "22006" should read --E2006--;  
Line 51, "(PIP)" should read --(PIF--; and  
Line 55, "E2026" should read --E2028--.

COLUMN 14

Line 2, "E2006" should read --E2008--;  
Line 4, "E22039." should read --E2039.--;  
Line 11, "mode" should read --mode--;  
Line 35, "SRAM." should read --SRAM--;  
Line 43, "control," should read --control--;  
Line 61, "E2003." should read --E2005.--; and  
Line 62, "data," should read --data--.

COLUMN 15

Line 41, "firs" should read --first--; and  
Line 56, "steps" should read --step--.

COLUMN 16

Line 16, "subscanning" should read --sub-scanning--.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO. US 6,874,864 B1**

No. of add'l. copies  
@ 30¢ per page

# UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO. : 6,874,864 B1

DATED : April 5, 2005

INVENTOR(S) : TETSUHIRO MAEDA ET AL.

Page 4 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 18

Line 34, "unit" should read --units--.

### COLUMN 24

Line 56, "other" should read --another--.

### COLUMN 25

Line 44, "14" should read --114--.

### COLUMN 26

Line 55, " $P(x, y) = f(\sqrt{(x - x_0 + 16)\%16^2 + \{(y - y_0 + 16)\%16\}^2})$ " should read  
 -- " $P(x, y) = f(\sqrt{\{(x - x_0 + 16)\%16\}^2 + \{(y - y_0 + 16)\%16\}^2})$ " --.

### COLUMN 27

Line 38, "wide" should read --wide by--.

### COLUMN 28

Line 25, "inverter" should read --inventor--.

### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
 30 Rockefeller Plaza  
 New York, New York 10112-3801  
 (212) 218-2100 - Telephone  
 (212) 218-2200 - Facsimile

PATENT NO. US 6,874,864 B1

No. of add'l. copies  
 @ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,874,864 B1

DATED : April 5, 2005

INVENTOR(S) : TETSUHIRO MAEDA ET AL.

Page 5 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 29

Line 2, "this" should read --thus--; and

Line 61, "area" should read --areas--.

COLUMN 31

Line 60, "print" should read --print area--.

COLUMN 32

Line 57, "A ink" should read --An ink--.

COLUMN 33

Line 17, "area" should read --areas--;

Line 18, "other," should read --other, and--;

Line 28, "main" should read --main scan--; and

Line 49, "other," should read --other, and--.

COLUMN 35

Line 14, "different" should read --the different--; and

Line 43, "different" should read --the different--.

COLUMN 39

Line 40, "in" should read --is--.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO. US 6,874,864 B1**

No. of add'l. copies  
@ 30¢ per page

Staple  
Here  
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

**PATENT NO.** : 6,874,864 B1

**DATED** : April 5, 2005

**INVENTOR(S)** : TETSUHIRO MAEDA ET AL.

Page 6 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 44**

Line 5, "masks" should read --mask--.

**MAILING ADDRESS OF SENDER:**

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

**PATENT NO.** US 6,874,864 B1

No. of add'l. copies  
@ 30¢ per page

